

The Coal Authority,
Mining Reports Office,
200 LICHFIELD LANE,
BERRY HILL,
MANSFIELD,
NOTTINGHAMSHIRE,
NG18 4RG
Telephone: 0845 762 6848
DX 716176 MANSFIELD 5
On-Line Service: www.coalminingreports.co.uk

The
**COAL
AUTHORITY**



The Coal Authority	
Cost:	£38.30
Plus V.A.T.	£6.70
Total Received:	£45.00
V.A.T. Reg Number	598 5850 68

URS THORBURN COLQUHOUN LTD,
URS THORBURN ASSOCIATES LTD,
KINNEIL HOUSE,
243 WEST GEORGE STREET,
GLASGOW,
LANARKSHIRE,
G2 4QE

This matter is being dealt with by Louise Tipper

Our Ref: **485466-02**

Your Ref: 48030 013

Electronic Ref:

Date: 18 November 2002

Dear Sir,

Coal Mining Report

I refer to the enquiry dated 15th November 2002, received 15th November 2002, in connection with the above.

This report is based on and limited to the records in the possession of The Coal Authority at the time the search is answered.

Past Underground Mining

The property is within the likely zone of influence on the surface from workings in 6 seams of coal at shallow to 150m depth, the last date of working being 1929.

Present Underground Mining

The property is not within the zone of likely physical influence on the surface from any present underground coal workings.

Future Underground Mining

The property is not within a geographical area for which a licence to extract coal by underground methods is awaiting determination by the Coal Authority.

The property is not within a geographical area for which a licence to extract coal by underground methods has been granted.

The property is not within the zone of likely physical influence at the surface from plans of future workings in our possession.

However reserves of coal exist in the locality which could be worked at some time in the future subject to feasibility, licences, and planning consents.

We have no record of any notice of the risk of the land being affected by subsidence being given under S.46 of the Coal Mining Subsidence Act 1991.

Shafts and Adits

Within or within 20 metres of the property there are 3 mine entries, the approximate positions of which are shown on the attached plan. Your attention is drawn to the statements made on that plan.

We have no record of what steps, if any, have been taken to treat the mine entries.

The records held by the Coal Authority may be incomplete. Consequently, there may exist in this locality mine entries of which we have no knowledge.

Surface Geology

Records in our possession do not disclose any fault or other line of weakness at the surface as having affected the stability of the property.

Past Opencast Mining

The property is not located within the geographical boundary of an opencast site from which coal has been extracted by opencast methods.

Present Opencast Mining

The property does not lie within 200 metres of the geographical boundary of an opencast site within which coal is being extracted by opencast methods.

Future Opencast Mining

The property is not within 800 metres of the geographical boundary of an opencast site for which a licence to extract coal by opencast methods is awaiting determination.

The property is not within 800 metres of the geographical site boundary of an opencast site for which a licence to extract coal by opencast methods has been granted.

Subsidence

The records in our possession do not disclose any damage notice or claim having been given, made or pursued in respect of the property since 1 January 1984.

The records in our possession do not disclose any current "Stop Notice" affecting the property.

The records in our possession do not show any request having been made to execute preventative works under S.33 of the Coal Mining Subsidence Act 1991.

Withdrawal of Support

The property does not lie within a geographical area in respect of which a notice of entitlement to withdraw support has been published.

The property does not lie within a geographical area in respect of which a notice has been given under S.41 of the Coal Industry Act 1994, revoking the entitlement to withdraw support.

Working Facilities Orders

The property is not within a geographical area that is the subject of an Order made under the provisions of the Mines (Working Facilities and Support) Acts 1923 and 1966 or any statutory modification or amendment thereof.

Payments to Owners of Former Copyhold Land

The property is not within an area where a relevant notice has been published under the Coal Industry Act 1975/Coal Industry Act 1994.

Additional Remarks

In view of the mining circumstances a prudent developer would seek appropriate technical advice before works are undertaken on site. All proposals should have regard to good engineering practice in mining areas as identified in authoritative publications on mining stability problems. In any event, no activities should be undertaken that intersect, disturb, or interfere with any coal or mines of coal without permission of the Coal Authority.

These replies are prepared in accordance with the Law Society's Guidance Notes 1998.


We acknowledge the receipt of your remittance in payment of our fee.

Yours faithfully

A handwritten signature in black ink, appearing to read 'A Schofield', written in a cursive style.

Albert Schofield

Director of Mining Records and Services



Crown Copyright. Quoted scale is approximate.

SCALE: 1:5000

This map is reproduced from the Ordnance Survey material by The Coal Authority [or division thereof] with the permission of the Controller of Her Majesty's Stationery Office. Crown Copyright. Unauthorised reproduction infringes Crown Copyright and may lead to prosecution or civil proceedings. Licence Number: AL51060A001.

This is a plan of the boundaries of the property in respect of which this report has been prepared. It is the responsibility of the user to ensure that the boundaries shown correspond with those of the property.

APPROXIMATE POSITION OF ENQUIRY BOUNDARY SHOWN



APPROXIMATE POSITION OF DISUSED MINE SHAFTS SHOWN



This plan shows the approximate location of the disused mine entry/entries referred to in the attached mining report. For reasons of clarity, mine entry symbols may not be drawn to the same scale as the plan. Property owners have the benefit of statutory protection (under the Coal Mining Subsidence Act 1991). This contains provision for the making good, to the reasonable satisfaction of the owner, of physical damage from disused coal mine workings including disused coal mine entries. A DTI leaflet setting out the rights and the obligations of either the Coal Authority or other responsible persons under the 1991 Act can be obtained by telephoning 0845 762 6848. If you wish to discuss the relevance of any of the information contained in the attached report you should seek the advice of a qualified mining engineer or surveyor. If you or your adviser wish to examine the source plans from which the information has been taken these are available at our Mansfield office, free of charge, by prior appointment, telephone 01623 638233. Should you or your adviser wish to carry out any physical investigations that may enter, disturb or interfere with any disused mine entry the prior permission of the owner must be sought. For coal mine entries the owner will normally be the Coal Authority. The Coal Authority, regardless of responsibility and in conjunction with other public bodies, provide an emergency call out facility in coalfield areas to assess the public safety implications of mining features (including disused mine entries). Our emergency telephone number at all times is 01623 646333.