


Shown are the projections of a component.
 Make a full size isometric drawing of the
 component having corner A as the lowest point.

UNIVERSITY of LIMERICK	
DRAWN:	ISOMETRIC DRAWING
COURSE:	DATE:
PROG. NO.	



DRAW, FULL SIZE, A COMPONENT WITH CORNER A

