

Scrap generation affects the equipment fraction calculation by...

- ☒ increasing the number of operations
- ☐ decreasing the reliability of the operation
- ☐ decreasing the efficiency of the operation
- ☐ all of the above

The reliability of a machine affects the...

- ☐ number of parts to process
- ☒ processing time of each part
- ☐ the availability of the machine
- ☐ none of the above

The efficiency of an operation affects the number of parts that need to be started in the system to satisfy a fixed quantity of good parts.

- ☐ True
- ☐ False

If a machine is shared between two different operations, the machine fraction is calculated for each operation independently and the sum of the rounded-up fractions provides the number of machines needed.

☐ True

☐ False